


RATING CHART

Resistance to Acids, Inorganic	Alcohols		
Carbonic Acid	E	Amyl Alcohol	E
Chlorine Water	E	Butyl Alcohol	E
Hydrobromic Acid	E	Ethyl Alcohol	E
Hydrochloric Acid	E	Methyl Alcohol	E
Hydrogen Sulfide	E	Propyl Alcohol	E
Phosphoric Acid	E	Benzyl Alcohol	E
Sulphuric Acid	E	Octyl Alcohol	E
Nitric Acid	E	Glycerin	E
Hydrofluoric Acid	E	Ethylene Glycol	E
		Diacetone Alcohol	E
		Triethanolamine	E
Inorganic Salts and Alkalis	Hydrocarbons		
Ammonium Hydroxide	E	Castor Oil	E
Potassium Hydroxide	E	Cocnut Oil	E
Sodium Hydroxide	E	Mineral Oil	E
Calcium Hypochlorite	E	Petroleum Oils	E
Ammonium Sulfate	E	Gasoline	F
Caustic Potash	E	Coal Tar Solvents	F
Copper Chloride	E	Naphtha	F
Copper Sulfate	E	Grease	E
Potassium Dichromate	E	Kerosene	G
Calcium Chloride	E	Turpentine	G
Ferric Chloride	E	Propane	E
Tin Chloride	E	Carbon Tetrachloride	G
Organic Materials	Trichloethylene	G	
Acetic Acid	E	Perchloroethylene	F
Citric Acid	E	Benzene	F
Formic Acid	E	Toluol	F
Lactic Acid	E	Toluene	F
Oleic Acid	E	Butane	G
Malic Acid	E	Hexane	G
Succinic Acid	E	Hylen	F
Tannic Acid	E	Cyclohexane	F
Carbolic Acid	E	Benzyl Chloride	E
Ketones and Aldehydes	Methyl Chloride	E	
Acetaldehyde	E	Chloroform	E
Butyraldehyde	E	Organic Esters	
Formaldehyde	E	Amyl Acetate	G
Furfural	E	Butyl Acetate	G
Benzaldehyde	E	Ethyl Acetate	G
Acetone	F	Methyl Acetate	G
Methyl Ethyl Keytone	G	Propyl Acetate	G
Chloroacetone	G	Ethyl Formate	G

E-Excellent G-Good F-Fair P-Poor

Proper care :

Easily cleaned with a mild detergent, warm water and a sponge.
In a machine use a medium water temperature not to exceed 120 C.
For best results, air drying is recommended.



WCSLPVC01 ชุดเสื้อกางเกง ตัวเสื้อแบบซีปรูตและติดกระดุมด้านนอก มีชุดคลุมศีรษะ size M,L แขนด้านในเป็นยางยืดมีช่องระบายอากาศ ด้านหลังและใต้รักแร้ กางเกง แบบยางยืดใช้สวมคลุมทับชุดทำงาน



WSCOPVC02 ชุดหมี่พีวีซีเต็มตัว ปกป้อง 2 ชั้น ด้วยซีปด้านใน กระดุมด้านนอก ส่วนแขน ขาด้านในเป็นยางยืด



WSCOPVC03 ชุดคลุมยาวใช้สวมทับชุดทำงาน



WSAPPVC01
เอี๊ยมพีวีซี
ขนาด
70 x 100
เซนติเมตร

Body Protection

ชุดป้องกันสำหรับงานทั่วไป



- TT-COVER02** ชุดหมี่ผ้าเต็มตัวแบบเปิดหลัง
- TT-COVER01** ชุดหมี่ท่อนเต็มตัวแบบเปิดหลัง
- TT-APR01** เอี๊ยมหมี่ท่อนมีผ้าซับใน
- TT-APRFUR** เอี๊ยมหมี่เพอร์นิเจอร์
- TT-HOOD02** ชุดหมี่ผ้าคลุมศีรษะ
- TT-SLV01** ปลอกแขนหมี่ท่อน (คู่)
- TT-COS01** สนับขาหมี่ท่อน (คู่)
- PS-AL6** ชุดอลูมิเนียมป้องกันความร้อน
- PS-AL7** เอี๊ยมอลูมิเนียมกันความร้อน
- PS-AL8** ปลอกแขนอลูมิเนียมกันความร้อน
- PS-AL5** สนับขาสูไนซ์
- OT-SLV-J** ปลอกแขนผ้าใยสังเคราะห์

- OT-COA01** ชุดช่างเต็มตัวแบบติดกระดุมแขนปล่อย
- OT-COA02** ชุดช่างเต็มตัวแบบรูตซีปแขนจัม
- OT-NORMEXIII** ชุดช่างผ้า Normex III กันไฟ

